


4C90C
/

P24020.A21



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s) : S. J. HAN et al.

Certificate of Correction Branch

Patent No. : 6,884,977 B2

Issued: April 26, 2005

Serial No. : 10/630,659

Filed: July 31, 2003

For : VARIABLE-FREQUENCY INVERTER MICROWAVE OVEN AND
METHOD FOR CONTROLLING THE SAME

COVER LETTER FOR REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Sir:

Attached are a Request and a proposed Certificate of Correction in connection with the
above-identified patent.

A check in the amount of \$100.00 is enclosed to cover the fee. The Commissioner is hereby
authorized to charge any additional fees, or credit any overpayment, to Deposit Account No. 19-
0089.

Respectfully submitted,
S. J. HAN et al.




Bruce H. Bernstein
Reg. No. 29,027

October 26, 2005
GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191
(703) 716-1191

Steven Wegman
Reg. No. 31,438

*Certificate
OCT 28 2005
of Correction*



P24020.A20

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor(s) : S. J. HAN et al.

Certificate of Correction Branch

Patent No. : 6,884,977 *B2*

Issued: April 26, 2005

Serial No. : 10/630,659

Filed: July 31, 2003

For : VARIABLE-FREQUENCY INVERTER MICROWAVE OVEN AND
METHOD FOR CONTROLLING THE SAME

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following errors appearing in the printed patent which are apparently the fault of the U.S. Patent and Trademark Office, as per the attached Certificate of Correction.

At column 8, line 30 (claim 1, line 1) of the printed patent, "ovens" should be ---oven,---.

This appeared correctly on page 2, line 5 of the Response Under 37 C.F.R. 1.111 filed October 25, 2004.

At column 8, line 49 (claim 1, line 19) of the printed patent, before "magnetron" insert ---a---.

This appeared correctly on page 3, line 1 of the Response Under 37 C.F.R. 1.111 filed October 25, 2004.

10/27/2005 HLE333 00000027 6884977

01 FC:1811

100.00 0P

P24020.A20

At column 9, line 19 (claim 6, line 5) of the printed patent, before "raise" insert ---to---. This appeared correctly on page 4, line 16 of the Response Under 37 C.F.R. 1.111 filed October 25, 2004.

The following errors are apparently the fault of the Inventor(s):

On the cover of the printed patent, at Item (73), Assignee, "Electronic" should be ---Electronics---. This appeared incorrectly on the Form PTOL-85B filed March 22, 2005.

At column 10, line 37 (claim 14, line 1) of the printed patent, after "oven" insert ---of---. This appeared incorrectly on page 7, line 9 of the Response Under 37 C.F.R. 1.111 filed October 25, 2004.

Therefore, it is respectfully requested that a Certificate of Correction issue in the above-identified patent as follows:

At column 8, line 30 (claim 1, line 1) of the printed patent, "ovens" should be ---oven,---.

At column 8, line 49 (claim 1, line 19) of the printed patent, before "magnetron" insert ---a---.

At column 9, line 19 (claim 6, line 5) of the printed patent, before "raise" insert ---to---.


On the cover of the printed patent, at Item (73), Assignee, "Electronic" should be ---Electronics---.

At column 10, line 37 (claim 14, line 1) of the printed patent, after "oven" insert ---of---.

P24020.A20

Should there be any questions, the Examiner is invited to contact the undersigned at the below-listed number.

Respectfully submitted,
S. J. HAN et al.



Bruce H. Bernstein
Reg. No. 29,027

Steven Wegman
Reg. No. 31,438

October 26, 2005
GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191
(703) 716-1191

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTIONPATENT NO. : 6,883,345 *B2*Page 1 of 1

APPLICATION NO.: 10/447960

ISSUE DATE : April 26, 2005

INVENTOR(S) : C. S. LEE

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 8, line 30 (claim 1, line 1) of the printed patent, "ovens" should be ---oven,---.

At column 8, line 49 (claim 1, line 19) of the printed patent, before "magnetron" insert ---a---.

At column 9, line 19 (claim 6, line 5) of the printed patent, before "raise" insert ---to---.

On the cover of the printed patent, at Item (73), Assignee, "Electronic" should be ---Electronics---.

At column 10, line 37 (claim 14, line 1) of the printed patent, after "oven" insert ---of---.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

OCT 31 2005

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTIONPage 1 of 1

PATENT NO. : 6,883,345 B2

APPLICATION NO.: 10/447960

ISSUE DATE : April 26, 2005

INVENTOR(S) : C. S. LEE

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 8, line 30 (claim 1, line 1) of the printed patent, "ovens" should be ---oven,---.

At column 8, line 49 (claim 1, line 19) of the printed patent, before "magnetron" insert ---a---.

At column 9, line 19 (claim 6, line 5) of the printed patent, before "raise" insert ---to---.

On the cover of the printed patent, at Item (73), Assignee, "Electronic" should be ---Electronics---.

At column 10, line 37 (claim 14, line 1) of the printed patent, after "oven" insert ---of---.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C.
1950 Roland Clarke Place
Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

OCT 31 2005